

Run order

Heat 1	PF, PA, TM, PR
Heat 2	SR, SF, SA
Heat 3	MA, MF, UTV, MR

Work Order

Heat 1	SR, SF, SA
Heat 2	MA, MF, UTV, MR
Heat 3	PF, PA, TM, PR